Shipper Short Code	Rejection Reason	Number of Rejections
	- rejourni reason -	rejections
829	MPRN is not identified as class 1 site	729
	New corrected reading is less than previous corrected reading	265
	New Meter Reading is less than previous meter reading	267
	New uncorrected reading is less than previous uncorrected	7
	Reading Breached the lower Outer Tolerance	295
	Reading Breached the upper Inner Tolerance value and no	1
	Reading Breached the upper Outer Tolerance	18
Total	Treating District and appear outer releases	1,582
151	Meter point has no read to be replaced	1
	The convertor serial number on the read does not agree with	
	the convertor serial number held on the Transporter Database	1
	The meter serial number on the read does not agree with the	
	meter serial number held on the Transporter Database	1
Total		3
303	Meter, convertor corrected and uncorrected reads not	1
	MPRN is not identified as class 1 site	31
	The convertor uncorrected read has not been supplied where	
	there is a convertor fitted and the convertor reads are usable	1
Total		33
536	MPRN is not identified as class 1 site	6
	MPRN is not identified as class 1 site	6
Total		0
212	Meter, convertor corrected and uncorrected reads not	242
	MPRN is not identified as class 1 site	421
	Overide tolerance passed and override flag provided	22
	Reading Breached the upper Inner Tolerance value and no	13
	Reading Breached the upper Outer Tolerance	4
	The convertor corrected read does not have the expected	8
	The convertor corrected read has not been supplied where	
	there is a convertor fitted and the convertor reads are usable	4
	The convertor round the clock count has not been supplied	4
	The convertor serial number has not been supplied where	4
	The convertor uncorrected read has not been supplied where	
	there is a convertor fitted and the convertor reads are usable	242
Total		964
132	Meter point has no read to be replaced	61
	MPRN is not identified as class 1 site	221
	New corrected reading is less than previous corrected reading	22
	New Meter Reading is less than previous meter reading	12
	Overide tolerance passed and override flag provided	1
	Reading Breached the lower Outer Tolerance	22
	Reading Breached the upper Outer Tolerance	13
Total	Treading Drodenies and appear outer releases	352
373	Meter, convertor corrected and uncorrected reads not	51
	MPRN is not identified as class 1 site	253
	New corrected reading is less than previous corrected reading	1
	New Meter Reading is less than previous meter reading	1
	Reading Breached the lower Outer Tolerance	2

	Reading Breached the upper Outer Tolerance	19
	Reading is higher than a subsequent actual valid meter	2
	The converter corrected read has not been supplied where	
	there is a converter fitted and the converter reads are usable	23
	The convertor corrected read does not have the expected	34
	The convertor corrected read has not been supplied where	
	there is a convertor fitted and the convertor reads are usable	22
	The convertor round the clock count has not been supplied	22
	The convertor serial number has not been supplied where	22
	The convertor uncorrected read does not have the expected	34
	The convertor uncorrected read has not been supplied where	0.1
	there is a convertor fitted and the convertor reads are usable	51
	The meter read does not have the expected number of digits	16
Total	The meter read does not have the expected number of digits	553
- Otal		000
333	Asset activity recorded for read date	1
	Meter Read Reason invalid for a Gas Card read	2
	Meter Serial number is for a previous meter	4
	Meter, convertor corrected and uncorrected reads not	19
	MPRN is not identified as class 1 site	128
	MPRN received in an incorrect file based on its class on the	2
	New corrected reading is less than previous corrected reading	5
	New Meter Reading is less than previous meter reading	17
	New uncorrected reading is less than previous uncorrected	7
	Read date lies within a consumption adjusted period	7
	Reading Breached the lower Outer Tolerance	8
	Reading Breached the upper Inner Tolerance value and no	10
	Reading Breached the upper Outer Tolerance	11
	Reading is higher than a subsequent actual valid meter	1
	The convertor corrected read does not have the expected	63
	The convertor serial number on the read does not agree with	
	the convertor serial number held on the Transporter Database	3
	The convertor uncorrected read does not have the expected	44
	The convertor uncorrected read has not been supplied where	
	there is a convertor fitted and the convertor reads are usable	19
	The Meter Point already has a read for this date	9
	The meter read does not have the expected number of digits	34
	The meter serial number on the read does not agree with the	0.1
	meter serial number held on the Transporter Database	39
Total	motor containment field on the Hamperton Battabace	433
. otal		.00
839	MPRN is not identified as class 1 site	33
Total		33
272	A convertor serial number has been supplied where no	6
	convertor corrected read has been supplied where no	6
	convertor Round the Clock Count should not be provided	6
	convertor uncorrected read has been supplied where no	6
	Meter does not exist	6
	Meter, convertor corrected and uncorrected reads not	6
	MPRN is not identified as class 1 site	617
	New corrected reading is less than previous corrected reading	3
	Read date lies within a consumption adjusted period	20
	Reading Breached the lower Outer Tolerance	4
	Reading Breached the upper Inner Tolerance value and no	11

	The convertor corrected read has not been supplied where	
	there is a convertor fitted and the convertor reads are usable	6
	The convertor round the clock count has not been supplied	6
	The convertor serial number has not been supplied where	6
	The convertor serial number on the read does not agree with	
	the convertor serial number held on the Transporter Database	113
	The convertor uncorrected read does not have the expected	360
	The convertor uncorrected read has not been supplied where	
	there is a convertor fitted and the convertor reads are usable	6
	The Meter Point already has a read for this date	1
	The meter serial number on the read does not agree with the	
	meter serial number held on the Transporter Database	90
Total		1,279
920		1
020	Meter, convertor corrected and uncorrected reads not	84
	MPRN is not identified as class 1 site	74
	The converter corrected read has not been supplied where	
	there is a converter fitted and the converter reads are usable	1
	The convertor corrected read does not have the expected	17
	The convertor uncorrected read has not been supplied where	
	there is a convertor fitted and the convertor reads are usable	84
Total	there is a convertor fitted and the convertor reads are asable	261
343	Meter point has no read to be replaced	185
	MPRN is not identified as class 1 site	3,161
	New corrected reading is less than previous corrected reading	7
	New Meter Reading is less than previous meter reading	8
	Overide tolerance passed and override flag provided	12
	Read date lies within a consumption adjusted period	6
	Reading Breached the lower Outer Tolerance	11
	Reading Breached the upper Inner Tolerance value and no	6
	Reading Breached the upper Outer Tolerance	2
	The converter corrected read has not been supplied where	
	there is a converter fitted and the converter reads are usable	4
	The convertor corrected read does not have the expected	3
	The convertor serial number on the read does not agree with	
	the convertor serial number held on the Transporter Database	11
	The convertor uncorrected read does not have the expected	3
	The meter serial number on the read does not agree with the	J
	meter serial number held on the Transporter Database	7
Total		3,426