

Shipper Short	Rejection Reason	Number of Rejections
151	Actual read can only be replaced by a replacement read.	10
	New Meter Reading is less than previous meter reading	47
	New uncorrected reading is less than previous uncorrected reading	43
	Non-opening reading received outside the read receipt window	4
	nxt mtr rd less than current and TTZ incorrect	1
	Reading breached the upper Inner tolerance value and no override flag provided.	28
	Reading breached the Upper Outer tolerance.	42
	The meter serial number on the read does not agree with the meter serial number held on the Transporter Database	6
		181
242	Actual read can only be replaced by a replacement read.	30
		30
617	Reading breached the upper Inner tolerance value and no override flag provided.	4
	Reading breached the Upper Outer tolerance.	61
		65
212		1
	Actual read can only be replaced by a replacement read.	9,012
	Asset activity recorded for read date	7
	Corrector corrected read has been supplied where no corrector is fitted	3
	Meter not found for Meter Point	4
	Meter Point status is not LI (Live)	6
	Meter read/Convertor read provided but asset number missing	3
	MPRN received in an incorrect file based on its class on the read date	158
	New Meter Reading is less than previous meter reading	62
	New uncorrected reading is less than previous uncorrected reading	2
	Non-opening reading received outside the read receipt window	12,496
	Reading Breached the lower Outer Tolerance	2
	Reading Breached the upper Inner Tolerance value and no override flag provided	5
	Reading breached the upper Inner tolerance value and no override flag provided.	8,674
	Reading Breached the upper Outer Tolerance	6
	Reading breached the Upper Outer tolerance.	718
	The meter read does not have the expected number of digits	7
	The meter serial number on the read does not agree with the meter serial number held on the Transporter Database	6
		31,172
121	Meter, Convertor corrected and uncorrected reads not provided where DRE not present.	2

	The convertor serial number has not been supplied where there is a convertor is fitted	1
	The convertor serial number on the read does not agree with the convertor serial number held on the Transporter Database	1
	The corrector round the clock count has not been supplied	1
		5
223	Meter point has no read to be replaced	1
	MPRN received in an incorrect file based on its class on the read date	61,904
	Reading breached the upper Inner tolerance value and no override flag provided.	4
	The Meter Point already has an opening read for this date	1
	The meter read does not have the expected number of digits	1
	The meter read has a future read date	4
	The meter read reason is invalid	1
		61,916
181	Actual read can only be replaced by a replacement read.	1
	Non-opening reading received outside the read receipt window	12
	Reading breached the upper Inner tolerance value and no override flag provided.	3
	Reading breached the Upper Outer tolerance.	2
		18
526	MPRN received in an incorrect file based on its class on the read date	6
	The Meter Point already has an opening read for this date	1
	The meter read reason is invalid	1
		8
272	Non-opening reading received outside the read receipt window	19
	Reading breached the upper Inner tolerance value and no override flag provided.	2
	Reading breached the Upper Outer tolerance.	3
	The meter read source is invalid	2
		26
920		1
	Actual read can only be replaced by a replacement read.	694
	Asset activity recorded for read date	2
	Corrector corrected read has been supplied where no corrector is fitted	1
	Meter Point status is not LI (Live)	1
	Meter read/Convertor read provided but asset number missing	1
	MPRN received in an incorrect file based on its class on the read date	145
	New Meter Reading is less than previous meter reading	14
	Non-opening reading received outside the read receipt window	5,549
	nxt mtr rd less than current and TTZ incorrect	1

	Reading Breached the upper Inner Tolerance value and no override flag provided	2
	Reading breached the upper Inner tolerance value and no override flag provided.	1,963
	Reading breached the Upper Outer tolerance.	241
	The meter read does not have the expected number of digits	2
	The meter serial number on the read does not agree with the meter serial number held on the Transporter Database	4
		8,621
272	A convertor serial number has been supplied where no convertor is fitted	6
	convertor corrected read has been supplied where no convertor is fitted	6
	convertor Round the Clock Count should not be provided where a convertor is not fitted	6
	convertor uncorrected read has been supplied where no convertor is fitted.	6
	Meter does not exist	6
	Meter, convertor corrected and uncorrected reads not provided where DRE not present.	6
	MPRN is not identified as class 1 site	617
	New corrected reading is less than previous corrected reading	3
	Read date lies within a consumption adjusted period	20
	Reading Breached the lower Outer Tolerance	4
	Reading Breached the upper Inner Tolerance value and no override flag provided	11
	The convertor corrected read has not been supplied where there is a convertor fitted and the convertor reads are usable	6
	The convertor round the clock count has not been supplied	6
	The convertor serial number has not been supplied where there is a convertor is fitted	6
	The convertor serial number on the read does not agree with the convertor serial number held on the Transporter Database	113
	The convertor uncorrected read does not have the expected number of digits	360
	The convertor uncorrected read has not been supplied where there is a convertor fitted and the convertor reads are usable	6
	The Meter Point already has a read for this date	1
	The meter serial number on the read does not agree with the meter serial number held on the Transporter Database	90
Total		1,279
920		1
	Meter, convertor corrected and uncorrected reads not provided where DRE not present.	84
	MPRN is not identified as class 1 site	74
	The converter corrected read has not been supplied where there is a converter fitted and the converter reads are usable	1

	The convertor corrected read does not have the expected number of digits	17
	The convertor uncorrected read has not been supplied where there is a convertor fitted and the convertor reads are usable	84
Total		261
343	Meter point has no read to be replaced	185
	MPRN is not identified as class 1 site	3,161
	New corrected reading is less than previous corrected reading	7
	New Meter Reading is less than previous meter reading	8
	Override tolerance passed and override flag provided	12
	Read date lies within a consumption adjusted period	6
	Reading Breached the lower Outer Tolerance	11
	Reading Breached the upper Inner Tolerance value and no override flag provided	6
	Reading Breached the upper Outer Tolerance	2
	The converter corrected read has not been supplied where there is a converter fitted and the converter reads are usable	4
	The convertor corrected read does not have the expected number of digits	3
	The convertor serial number on the read does not agree with the convertor serial number held on the Transporter Database	11
	The convertor uncorrected read does not have the expected number of digits	3
	The meter serial number on the read does not agree with the meter serial number held on the Transporter Database	7
Total		3,426